

USER MANUAL

PRECAUTIONS

Never load the scale with more than the maximum capacity. Overloading will permanently damage it!

Always keep your scale in a clean environment. Dust, dirt, moisture, vibration, air currents and a close distance to other electronic equipment can all cause an adverse effect on the reliability and accuracy of your scale.

Avoid shaking, dropping, or subjecting the scale to shocks. This is a precision instrument and must be handled with extreme care.

Only operate the scale on a stable, vibration-free surface.

WEIGHING

1. Unlock for use by using the red switch located under the scale.
2. Place the scale on a horizontal flat surface, press [ON/OFF].
3. Wait until "0.0" is displayed.
4. Put the object(s) on the weighing platform.
5. Using the [UNIT] key, you can switch between the weighing units.

TARE WEIGHING

1. Turn on the scale as described above.
2. Place the tare item on the platform.
3. Press [ZERO] and wait until "0.0" is displayed.
4. Add the item to be weighed.

CALIBRATION

1. Turn on the scale by pressing [ON/OFF] key.
2. Wait until the LCD displays "0.0" and then press and hold [UNIT] key for 3 seconds. The LCD will display "CAL", and then release the [UNIT] key.
3. Press [UNIT] key again. The LCD will display "CAL" followed by the required calibration weight.
4. Add the required calibration weight. The display will show "PASS" and return to normal weighing mode.
5. Put away the calibration weight and press [ON/OFF] to turn off the scale and the calibration is finished.

TRANSPORTATION

During the transportation, please protect the loadcell by using the red switch located under the scale.

MANUEL D'UTILISATION

PRÉCAUTIONS

Ne jamais charger la balance avec un poids supérieur à sa capacité maximale. Une surcharge peut l'endommager de façon permanente.

Conservez la balance dans un environnement propre. La poussière, l'humidité, les vibrations, les courants d'air et la proximité d'autres équipements électroniques peuvent nuire à la fiabilité et à la précision de votre balance.

Évitez de secouer, de faire tomber ou de soumettre la balance à des chocs. C'est un instrument de précision qui doit être manipulé avec soin.

N'utilisez la balance que sur une surface stable et sans vibrations.

PESÉE

1. Déverrouillez la balance en utilisant l'interrupteur rouge situé sous l'appareil.
2. Placez la balance sur une surface plane et horizontale, puis appuyez sur [ON/OFF].
3. Attendez que « 0.0 » s'affiche.
4. Placez l'objet à peser sur le plateau.
5. À l'aide de la touche [UNIT], vous pouvez changer l'unité de mesure.

PESÉE AVEC TARE

1. Allumez la balance comme indiqué ci-dessus.
2. Placez la tare sur le plateau.
3. Appuyez sur [ZERO] et attendez que « 0.0 » s'affiche.
4. Ajoutez l'objet à peser sur le plateau.

CALIBRAGE

1. Allumez la balance en appuyant sur la touche [ON/OFF].
2. Attendez que l'écran LCD affiche « 0.0 », puis maintenez la touche [UNIT] enfoncée pendant 3 secondes. L'écran affichera « CAL », relâchez alors la touche [UNIT].
3. Appuyez de nouveau sur [UNIT]. L'écran affichera « CAL » suivi du poids de calibration requis.
4. Placez le poids de calibration requis. L'écran affichera « PASS » puis reviendra au mode de pesée normal.
5. Retirez le poids de calibration et éteignez la balance avec [ON/OFF]. La calibration est terminée.

TRANSPORT

Lors du transport, protégez le capteur en utilisant l'interrupteur rouge situé sous la balance.